

JOB SAFETY ANALYSIS

Job Description:

Block Change Out

Personal Protective Equipment Required or Recommended:

Hard Hat

Harness

Gloves

Steel Toe Boots

Safety Glasses

Fall Protection

Sequence Of Basic Job Steps:

Potential Accidents Or Hazards:

Recommendations To Eliminate Or

Reduce Hazards:

1. Hang both blocks	Pinch points, Falling	PPE, Use correct tools, Good Communication
2. Remove drill line from draw works	Pinch points	PPE, Use correct tools, Good Communication
3. Remove wraps from tie down	Pinch points,	PPE, Use correct tools, Good Communication
4. Attach snake	Slipping, Wear, Hang up points	PPE, Inspect snake and connectors
5. Unstring blocks	Falling line, Hang ups	PPE, Keep floor clear, Good Communication
6. Jump string-up line over Inspect Work	Falling, Pinch points, Crossed Line	PPE, Use correct equipment, Good communication,
7. String-up blocks	Hang-ups, Snake Breaking	PPE, Keep floor clear, Good communication